



February 28, 2006

William Bowers

Mason TN 38049-8210



Dear Harley-Davidson Owner,

We are pleased to be able to inform you that Harley-Davidson's Initial Care program related to your 2006 model Dyna motorcycle has now concluded.

This means that the additional maintenance requirements that were stipulated for your motorcycle are no longer needed. As you may recall, the Company initiated its Initial Care Program for the all-new 2006 Dyna family of motorcycles at the time of their introduction. Initial Care is a maintenance procedure that the Company implements at its discretion for significant changes or major new products to ensure that our customers have the highest possible level of satisfaction with their new motorcycles.

As a result of our ongoing testing on the 2006 Dyna models, we have now determined that the precautionary maintenance requirements we recommended during the Initial Care program are no longer required. The items affected are as follows:

- ◆ Inner primary bearing replacement at 15,000 mile intervals is no longer necessary.
- ◆ The fluid change intervals have been extended as follows:
 - The new Transmission oil change interval has been set at 20,000 miles.
 - The Inner Primary oil change interval has been set at 10,000 miles.

 - The Engine oil change interval remains at 5,000 miles, which is the standard requirement for all current production, street legal Harley-Davidson engines.

We hope you will make a note of these changes in your owners' manual or keep this letter with your manual.

Thank you for helping us ensure your continued happiness with your new motorcycle. We wish you many miles of riding pleasure on your new Harley!

Sincerely,

Harley-Davidson Motor Company, Inc.
Dyna-Initial Care Follow-up